

Automotive  
Rockwell International Corporation  
2135 West Maple Road  
Troy, MI 48084-7186  
(313) 435-2705



Rockwell  
International

April 19, 1994

REC'D  
IDEM OF  
APR 22 1994

RECEIVED  
WMD RECORD CENTER

JUN 02 1994

**CERTIFIED MAIL**

Rosemary W. Cantwell, Chief  
Hazardous Waste Section  
Office of Enforcement  
Indiana Department of Environmental Management  
100 North Senate Street  
Indianapolis, Indiana 46206-6015

Re: **Violation Letter VL-11773 Hazardous Waste Management**  
**Amland Facility-Mishawaka, Indiana**

IND 981091515

Dear Ms. Cantwell:

This letter is a follow-up to our February 14, 1994 response to the referenced violation letter. At our request, Geraghty & Miller, Inc. has revised and updated the post closure monitoring plan for the **Amland Corporation Site** in Mishawaka, Indiana. The revised plan is enclosed for your review and comment.

The revised plan was prepared in accordance with the RCRA Groundwater Monitoring: Draft Technical Guidance which was published by the USEPA in 1992. As you know the 1992 RCRA guidance is intended to supersede the Technical Enforcement Guidance Document (TEGD) which was originally prepared in 1986. The revised post closure monitoring plan also requires the use of USEPA SW-846 methods for the analysis of chromium and volatile organic compounds.

In addition to containing updated methods and procedures which are intended to properly operate and maintain the groundwater monitoring system for the next 20 years, the plan also provides a revised monitoring well system for the smaller configuration of the old settling basin. (The area of the basin was reduced by one-third when it was closed in late 1985 and early 1986.) The new monitoring system includes a new well (93A) between Wells 2A and 3A which will be installed in the near future.

Additionally, Rockwell and Chrysler intend and will continue to make repairs on monitoring wells, such as sealing Well 20B, marking survey points on each well, equipping the wells with vented caps and ensuring that the concrete surface pad at each well is intact. The sampling bailers will also be equipped with stainless steel and teflon leaders. These actions are being taken in response to the deficiencies noted in your violation letter dated January 10, 1994.

Sincerely,

AUTOMOTIVE,  
ROCKWELL INTERNATIONAL

P. Backlund  
AUTOMOTIVE  
ROCKWELL INTERNATIONAL

Enclosure:

PB/s

cc: (Cover ltr only) Richard R. Milton/IDEM; David Wersan/IDEM; Greg Romaine/IDEM; Lynn Buhl/Chrysler;  
Pat Mydlarz/Chrysler; J. A. Simmons/Ice, Miller, Donadio & Ryan; R. K. Beck/Rockwell Pitts.

Index: PAmland3